

October 8, 2009


IMPORTANT SAFETY NOTICE

SALOMON SAS ANNOUNCES A VOLUNTARY RECALL OF THE TOE COMPONENTS OF CERTAIN SKI BINDINGS MANUFACTURED BETWEEN JULY AND OCTOBER 2008.

In certain circumstances, the toe components of the below listed models may not fully secure the ski boot into the binding, possibly causing the binding to release inadvertently, posing a falling risk to the skier.

The SALOMON and ATOMIC binding models listed below were manufactured by Salomon and share the same toe piece construction.

The toe components of the following models are affected:

SALOMON  branded models are LZ 7, LZ 8, LZ 9, LZ 7 SR, LZ 8 SR, LZ 8 SC and JLZ 9



ATOMIC  branded models are Evox 2.8, Evox 2.8+, Evox 2.8++ and FFG8



The bindings subject to the recall bear a production date code, ending in the number "8" (for 2008), found on the center plate where the toe of the ski boot contacts the toe component of the binding.

Consumers should immediately stop using these ski bindings and bring the Salomon LZ bindings to an authorized SALOMON Ski Dealer, the Atomic Evox 2.8 and FFG8 bindings to an authorized ATOMIC Ski Dealer for a free replacement of the toe components.

For more information, including list of SALOMON, ATOMIC and INTERSPORT dealers, please go to www.salomon.com , www.atomicsnow.com

If you have any questions, you can call 1.800.361.3398 ext 3838 or send an e-mail to qualityinfo.canada@salomon-sports.com